

Healthy Homes Report for **73 MORROW AVE, ST ANDREWS**

Building & Summary




Address of Property Client Name 73 MORROW AVE, ST ANDREWS Waikato Real Estate Assessment Date Assessors Name 27/06/2024 Jonah Poloa

Photo of Front of House

GPS Location of Property





Healthy Homes Standards Overall Summary

• Insulation Standard

PASS Ceiling Insulation

Property is Compliant

The property currently has a Ceiling Insulation Rating of at least R2.9 and meets the intent of the NZS4246 standards.

PASS Underfloor Insulation

Property is Compliant

The property currently has an Underfloor Insulation Rating of at least R1.3 and meets the intent of the NZS4246 standards.

PASS Wall Insulation

Property is Compliant

Wall Insulation is currently complaint and/or status & condition cannot be determined without potential damage to the property or liability to the company or assessor.

Heating Standard

PASS

Heating

Property is Compliant

The property contains a qualifying heat source that meets or exceeds the minimum heating requirements, or meets 80% of requirements if installed prior to July 2019.

• Moisture Ingress & Drainage Standard

PASS

Vapour Barrier

Property is Exempt

The On-Ground Vapour Barrier is currently EXEMPT from meeting the mimumum insulation requirements as stated in NZS4246.

PASS

Drainage System

Property is Compliant

The property has an efficient drainage system, designed to remove excess water efficiently away from the property.

• Ventilation Standard

PASS

Extraction Fans

Property is Compliant

All Bathrooms and Kitchens have a qualifying, functioning extraction fan fitted that is vented to the outdoors.

PASS

Openable Windows

Property is Compliant

Each habitable space has 1 or more qualifying openable window(s) or door(s) and/or room(s) meet alternative ventilation requirements at time of lawful build.

• Draught Stopping Standard

PASS

Doors & Windows

Property is Compliant

The property is free from unintentional and unreasonable gaps between, and holes in, building elements that allow draughts into or out of the premises.

• Smoke Alarms (Residential Tenancy Act)

FAIL

Smoke Alarms

Property is NOT Compliant

The property DOES NOT contain smoke alarm(s) within 3 metre of each bedroom and/or contains one on each property level.



Insulation



Ceiling Insulation

Ceiling and Underfloor Insulation has been compulsory in all rental homes since 1 July 2019. Under the Healthy Homes Insulation Standard, existing insulation may need to be topped up or replaced if it is not in a reasonable condition. Existing ceiling insulation needs to be at least 120mm thick. If ceiling insulation needs to be topped up, it must meet minimum R-values for ceiling insulation as set out in the 2008 Building Code. Underfloor insulation needs to meet a minimum R-value of 1.3. If Foil insulation is installed it must be in good condition with significant no holes or tears.

HHS Compliancy PASS	Property is Compliant The property currently has a Ceiling Insulation Rating of at least R2.9 and meets the intent of the NZS4246 standards.
Existing Insulation Existing R-Rating (if known) Existing Thickness Overall Insulation Condition	GreenStuf R2.9 170mm Good
Install Date (if known)	
Additional Comments:	
Underfloor Insulation	
HHS Compliancy PASS	Property is Compliant The property currently has an Underfloor Insulation Rating of at least R1.3 and meets the intent of the NZS4246 standards.
Existing Insulation Type Existing Depth or R-Rating Overall Insulation Condition Install Date (if known)	Polyester R1.5 Good
Additional Comments:	
Wall insulation	
Statement the level of insulation present in the	Ithy Homes Standard, however it is a requirement that you include in the Healthy Homes Compliance e walls of the property. If you are unable to find out what level of insulation is in the walls (and have is acceptable to declare on the compliance statement that the level is unknown and give a reason.
HHS Compliancy PASS	Property is Compliant Wall Insulation is currently complaint and/or status & condition cannot be determined without potential damage to the property or liability to the company or assessor.
Existing Insulation Type Existing R-Rating	Unknown Unknown
Additional Comments:	



Heating



Heating

A rental home must have a fixed heating device (or devices) that can directly heat the main living room. This may be via a duct or vent located in the main living room. The fixed heating device(s) must be an acceptable type of heater and meet a required minimum heating capacity, or 80% if installed prior to July 2019. The heater CAN NOT be an open fire, un-flued gas heater or other un-flued combustion heater.

HHS Compliancy

PASS

Property is Compliant

The property contains a qualifying heat source that meets or exceeds the minimum heating requirements, or meets 80% of requirements if installed prior to July 2019.

Existing Heater Present
Existing Heating Output
Clean, Legal and Functional?
Install Date or Estimation

Fireplace 16.00kW Yes Unknown

<---->

Minimum Heating Capacity Requirement

9.00kW

Based on the Tenancy Heating Calculator

Additional Comments:

The living area is equipped with a heat pump and a woodburner, while the main bedroom has an additional heat pump.

Moisture & Drainage



On-Ground Vapour Barrier

If a home has a suspended floor (i.e. there is a cavity under the floor), and the subfloor space under the home is enclosed, then the home requires a ground vapour barrier. A subfloor is considered enclosed if the airflow into and out of the space is significantly obstructed along at least 50 per cent of the perimeter of the subfloor space.

HHS Compliancy



Property is Exempt

The On-Ground Vapour Barrier is currently EXEMPT from meeting the mimumum insulation requirements as stated in NZS4246.

Existing Condition Workspace Condition Subfloor Perimeter No O-Gvb Installed Workspace Insufficient Over 50% Obstructed

Additional	Comments:

Drainage

A rental property must: efficiently drain storm water, surface water and ground water to an appropriate outfall; and include appropriate gutters, downpipes, and drains to remove water from the roof. These gutters and downpipes must be free from obstructions i.e. leaf matter and other debris. Note: It has been a requirement for all homes to have efficient drainage for the removal of storm water, surface water and ground water since 1947 as part of the Housing Improvement Regulations 1947.

HHS Compliancy



Property is Compliant

The property has an efficient drainage system, designed to remove excess water efficiently away from the property.

Gutter Status	Clear and Flowing	>	Solution:
Downpipes	Clear and Flowing	>	Solution:
Drainage System	No Evidence of Issues	>	Solution:

Additional Comments:



Ventilation



Extractions Fans

The ventilation standard requires all kitchens with an indoor cooktop and bathrooms with a bath or shower need to have an extractor fan that ventilates extracted air to the outdoors and is in good working order. New kitchen fans installed after 1 July 2019 must have a minimum exhaust ducting diameter of 150mm or exhaust capacity of at least 50 litres per second. New bathroom fans installed after 1 July 2019 must have an exhaust diameter of 120mm or an exhaust capacity of 25 litres per second.

Property is Compliant

HHS Compliancy		Bathrooms and Kitcher coutdoors.	ns have a qualify	ving, functioning extraction fan fitted that is vented to
Kitchen Ventilation Present Fan Condition Ducting Status Installed Date	Rangehood Fully Functiona ≥150mm or 50 Unknown	al	> >	Solution: Solution:
Main Bathroom Ventilation Present Fan Condition Ducting Status Installed Date	Ceiling Fan Fully Functiona ≥120mm or 25 Unknown	al	> >	Solution: Solution:
No Additional Room(s) Ventilation Present Fan Condition Ducting Status Installed Date			> >	Solution: Solution: Solution:
No Additional Room(s) Ventilation Present Fan Condition Ducting Status Installed Date			> >	Solution: Solution:
Additional Comments:				

Openable Doors and Windows

To meet the healthy homes ventilation standard, the living room, dining room, kitchen and bedroom must have one or more windows, doors or skylights that are 'openable' - i.e, that open to the outdoors, allow the flow of air into and out of the property, and can be fixed in an open position. The combined area of openable windows and/or doors needs to be a minimum of 5% of that rooms floor area.

HHS Compliancy



Property is Compliant

Each habitable space has 1 or more qualifying openable window(s) or door(s) and/or room(s) meet alternative ventilation requirements at time of lawful build.

Location of Door/Window Openable & Meets 5% of Floor	ALL DOORS & WINDOWS Yes
Location of Door/Window Openable & Meets 5% of Floor	
Location of Door/Window Openable & Meets 5% of Floor	

NB: Additional rooms and locations are noted on the following page



Draughts



Doors and Windows

To meet the healthy homes draught stopping standard you need to block any unreasonable gaps or holes that allow draughts into or out of the property. This includes gaps or holes in walls, ceilings, windows, plumbing and electrical pipes, open fireplaces, floors and doors that are not necessary and cause noticeable draughts. These must be blocked. The standard uses the following guide to determine if a gap is unreasonable: Gaps or holes with a width greater than 3mm that let air into or out of the home will usually require blocking to prevent unreasonable draughts.

HHS Compliancy



Property is Compliant

The property is free from unintentional and unreasonable gaps between, and holes in, building elements that allow draughts into or out of the premises.

Location Any Gaps or Holes? Opens & Meets 5% Floor	ALL DOORS & WINDOWS None or less than 3mm Yes	>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Location Any Gaps or Holes? Opens & Meets 5% Floor		>	Solution:
Additional Comments:			



Smoke Alarms



Smoke Alarms

Please Note: Working smoke alarms are part of the Residential Tenancies Regulations 2016 – Smoke Alarm (Regulation 5), not the Healthy Homes Standards 2019. Working smoke alarms or detectors are compulsory in all rental homes. Smoke alarms must be installed: within 3 metres of each bedroom door, or in every room where a person sleeps; in each level or story of a multi-story or multi-level home. Working smoke alarms must: be photoelectric; have a battery life of at least eight years, or be hard-wired, installed according to the manufacturer's instructions, meet international standards and be within their expiry date.

HHS Compliancy



0

Property is NOT Compliant

The property DOES NOT contain smoke alarm(s) within 3 metre of each bedroom and/or contains one on each property level.

Number of Working Alarms # of 10 Year Alarms Oldest Alarm Date Earliest Replacement Date ----> Alarm Location 1
Alarm Location 2
Alarm Location 3
Alarm Location 4

None Present



Insulation



Ceiling Insulation Photos









Underfloor Insulation Photos









Moisture Ingress



On-Ground Vapour Barrier Photos









Heating



Heating Photos













Drainage



Drainage Photos









Ventilation



Extraction Fan Photos









Smoke Alarms



Smoke Alarm Photos

Doors and Windows



Openable Windows and Draught Proofing Photos

















